





**Viega PEX Crimp Supply adapter
Zero Lead**
 - For connecting PEX supply lines to Viega ManaBloc and Viega MiniBloc
 - PolyAlloy
 - Crimp connection, Viega ManaBloc supply connection
Model V5213

P	Supply	Wt [lb]	Quantity	Part No	DG
3/4	1	0.095	5	50141	2
1	1	0.100	5	50151	2



Viega ManaBloc Distribution manifold Zero Lead
 - Compression
 - Color coded ports for hot and cold water
 - Does not include supply connections
Components
 1/4 turn valves, T-handle valve key
Model V5030

Adapter	Port(s)	d	hot	cold	Wt [lb]	Quantity	Part No	DG
compression	14	3/8	6	8	5.280	1	36142	2
compression	18	3/8	8	10	6.201	1	36182	2
compression	24	3/8	9	15	7.774	1	36242	2
compression	30	3/8	12	18	9.117	1	36302	2
compression	36	3/8	14	22	10.958	1	36362	2
compression	14	1/2	6	8	5.578	1	36144	2
compression	18	1/2	8	10	6.463	1	36183	2
compression	24	1/2	9	15	8.158	1	36243	2
compression	30	1/2	12	18	9.887	1	36303	2
compression	36	1/2	14	22	11.537	1	36363	2



Viega ManaBloc Distribution manifold Zero Lead
 - Compression
 - Combination port sizes, color coded ports for hot and cold water
 - Does not include supply connections
Components
 1/4 turn valves, T-handle valve key
Model V5030.2

Adapter	Port(s)	d1	hot1	cold1	d2	hot2	cold2	Wt [lb]	Quantity	Part No	DG
compression	24	3/8	7	11	1/2	2	4	7.918	1	36624	2
compression	30	3/8	10	12	1/2	2	6	9.823	1	36630	2
compression	36	3/8	11	15	1/2	3	7	11.397	1	36636	2



Viega MiniBloc Zoning manifold Zero Lead
 - Compression
 - Blue color coded ports for cold water
 - Does not include supply connections
Components
 1/4 turn valves, T-handle valve key, optional red valve caps
Model V5031

Adapter	Port(s)	d	Wt [lb]	Quantity	Part No	DG
compression	3	3/8	2.024	1	36032	2
compression	4	3/8	2.234	1	36042	2
compression	6	3/8	2.918	1	36062	2
compression	8	3/8	3.549	1	36082	2
compression	3	1/2	2.119	1	36033	2
compression	4	1/2	2.344	1	36043	2
compression	6	1/2	2.900	1	36063	2
compression	8	1/2	3.829	1	36083	2